

Drill chuck connections



Morse Taper 2 to B16
Spindle connection
B16-MC2



Morse Taper 3 to B16
Spindle connection
B16-MC3



Morse Taper 2 to 1/2" x 20 UNF
Spindle connection
1/2UNF-MC2



Morse Taper 3 to 1/2" x 20 UNF
Spindle connection
1/2UNF-MC3

Morse Taper 2 to B18
Spindle connection
B18-MC2

Morse Taper 3 to B18
Spindle connection
B18-MC3

Twist drill chucks



Drill chuck
DIA Ø 1.5 - 13 mm,
1/2" x 20 UNF connection
IBK.13



Drill chuck quick connect
DIA Ø 2 - 13 mm
1/2" x 20 UNF connection
Keyless
IBK.13Q



Drill chuck
DIA Ø 1.5 - 13 mm
B16 connection
IBK.13-B16



Drill chuck
DIA Ø 1.5 - 16 mm
B16 connection
IBK.16



Drill chuck quick connect
DIA Ø 1.5 - 13 mm
1/2" x 20 UNF connection
Keyless
IBQ.13



Drill chuck quick connect
DIA Ø 1.5 - 16 mm
B16 connection
Keyless
IBQ.16

The IBQ.13 and IBQ.16 Quick connect drill chucks are keyless, three-jaw, self-centering chucks that hold drill bits in place during drilling tasks. They can be used with magnetic drilling machines together with Euroboor accessories like IBK.14, IBK.15 and 1/2" x 20 UNF Morse Taper.